

**Building Renewal Grant Application**

**Initial Submission Date:** 12/12/2012 3:52:29 PM

**Application ID:** 466

**Resubmittal Date:**

Please provide as much of the requested information as possible. SFB staff will assist in developing required information that is not currently available.

**District Name:** Cedar Unified District  
**Superintendent:** Dr. Kimberly Randall  
**Contact Person:** Henrietta Keyannie  
**Contact Phone Number:** 928-738-2367  
**Contact Email:** hettak11@gmail.com  
**School Site:** Jeddito School  
**Buildings:** 9999 School Wide

**Description of Problem**

Please include a detailed description of the issues, as well as a description of and a copy of any professional studies, citations or reports from government entities, recommended solutions, and any cost information or estimates. If additional space is needed, please attach.

Replace the fire pump generator control board. Generator will not automatically start without this replacement.

**Project Category:** Special Equipment

**Are any of the above-described issues in buildings or part of buildings that are leased to another entity, including a district sponsored charter school?** N

**Available Funding**

Current unencumbered building renewal fund balance (Fund 690):	\$0.00
Amount of Local funds planned for this project	\$0.00

Please outline any associated insurance coverage.

This board will not be covered as it was wear and tear. No other funding available for replacement.

**Liaison:** Cruse pcruse@azsfb.gov 602-364-1193

\_\_\_\_\_  
Superintendent Printed Name

\_\_\_\_\_  
Superintendent Signature

\_\_\_\_\_  
Date